

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Wednesday, September 12, 2018	Project Contact:	Brian Clauto
Spread: Franklin County	Spread I	Weather (Wet/Dry/Rain):	Wet

STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Clearing
 ☐ Rough Grading
 ☐ Trench Excavation
 ☐ Pipe Assembly, Testing & Installation
☐ Backfilling and Grade Restoration
 ☐ Final Grading & Stabilization
 ☒ Other: Storm prep


- | | Yes | No | N/A |
|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3 Areas of offsite sediment deposition were observed? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

Comments / Observations:

- **Area 1** – MP 263 slope drain dewatering sump installed at St# 13887+00
- **Area 2** - MP 261 St# 13816+00 sump is full. **Recommended Corrective Action** clean out sump, install adequate sump for drainage area ASAP per site conditions. Sediment below this area has been previously identified.
- **Area 3** - MP 255.40 Cahas Mtn Rd, additional controls have been installed at CE.

Deadline: Within 24hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:  Date: 9-17-18

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, September 12, 2018

Fig. 1
MP 263 slope drain dewatering sump installed at St# 13887+00



Fig. 2
MP 261 St# 13816+00 sump is full



Fig. 3
MP255.40 Cahas Mtn Rd, additional controls have been installed at CE.



Fig. 4